

AMENDMENTS TO THE SPECIFICATION

Please replace the paragraph beginning on page 11, line 19, with the following amended paragraph:

The aforementioned refill cartridge 120, as shown in FIG. 11, is built in the tape cassette 156 in such a manner that the first fork pipe 121 is inserted into the first rotational shaft 91, the second fork pipe 122 is inserted into the second rotational shaft 123, and the third fork pipe 123 is inserted into the third rotational shaft 93. The tapes 132a, 132b, . . . wound in the refill cartridge by driving of the tape cassette driver 70 are outwardly ejected through the ejection roller assembly 95 and the ejection outlet 125. Because the ejection roller assembly 95 is located outside of the refill cartridge 120, the ejection roller assembly does not contact first and second sheets 127a and 127b.